

	part	angle	FabTime	ExtTime	AirTime	RunTime	CoolTime
0	adfoot	0	90.27	88.60	1.67	17.26	13.97
1	adfoot	90	90.82	89.07	1.75	19.95	8.70
2	bkwren	0	143.87	138.45	5.42	38.16	14.95
3	bkwren	90	134.19	133.32	0.87	19.57	6.66
4	cthang	0	125.62	124.21	1.42	39.94	7.39
5	cthang	90	132.95	123.16	9.80	61.58	14.85
6	dstop1	0	49.31	47.09	2.22	22.84	14.98
7	dstop1	90	47.74	46.12	1.62	20.42	5.82
8	dstop2	0	30.87	29.60	1.26	16.94	4.28
9	dstop2	90	28.60	27.08	1.52	14.01	8.55
10	flange	0	180.80	169.04	11.75	49.33	14.78
11	flange	90	177.81	172.41	5.40	52.27	12.27
12	hlatch	0	164.09	161.28	2.81	35.09	13.30
13	hlatch	90	167.01	158.30	8.71	28.88	14.82
14	ladder	0	25.05	22.30	2.75	44.41	12.15
15	ladder	90	23.00	21.05	1.95	17.27	2.56
16	nkhang	0	131.65	127.66	3.99	31.66	14.73
17	nkhang	90	147.13	137.69	9.44	74.95	14.74
18	runleg	0	184.44	177.38	7.06	91.64	10.39
19	runleg	90	201.67	162.09	39.58	88.20	14.96
20	tkwren	0	50.90	48.90	2.00	12.78	14.15
21	tkwren	90	57.11	54.47	2.64	31.54	9.90
22	unwren	0	39.80	36.60	3.20	38.61	6.85
23	unwren	90	34.51	29.21	5.30	17.56	14.47