

	part	angle	FabTime	ExtTime	AirTime	RunTime	CoolTime
0	runleg	0	191.77	176.80	14.97	27.57	2.99
1	runleg	90	-	-	-	20.66	-
2	adfoot	0	104.33	86.36	17.97	4.48	2.98
3	adfoot	90	100.01	87.80	12.22	5.40	2.98
4	nkhang	0	-	-	-	8.15	-
5	nkhang	90	215.49	133.06	82.44	19.95	3.00
6	ladder	0	35.65	21.09	14.56	13.61	2.94
7	ladder	90	23.98	20.90	3.08	5.40	1.88
8	dstop2	0	32.54	29.25	3.29	5.22	2.70
9	dstop2	90	30.25	26.87	3.38	4.35	2.98
10	cthang	90	-	-	-	16.42	-
11	cthang	0	134.10	123.31	10.78	12.19	2.93
12	unwren	90	46.18	28.96	17.21	4.62	3.00
13	unwren	0	41.91	36.32	5.60	11.45	2.98
14	dstop1	0	59.76	46.18	13.58	6.62	3.00
15	dstop1	90	48.90	45.96	2.94	6.26	3.00
16	bkwren	90	139.18	133.21	5.97	5.98	2.99
17	bkwren	0	175.89	136.87	39.02	10.65	2.98
18	flange	0	-	-	-	12.47	-
19	flange	90	194.53	171.19	23.34	14.35	3.00
20	tkwren	90	60.43	54.08	6.35	9.20	2.95
21	tkwren	0	59.80	47.96	11.84	3.77	2.97
22	hlatch	90	-	-	-	7.78	-
23	hlatch	0	170.18	161.03	9.15	10.55	2.99