

	part	angle	FabTime	ExtTime	AirTime	RunTime	CoolTime
0	adfoot	0	90.61	88.60	2.01	5.66	14.61
1	adfoot	90	91.25	89.00	2.25	6.54	12.41
2	bkwren	0	146.11	138.33	7.77	11.47	13.10
3	bkwren	90	134.65	133.28	1.37	6.48	6.66
4	cthang	0	128.11	123.62	4.48	12.61	6.19
5	cthang	90	133.74	122.97	10.77	17.28	14.92
6	dstop1	0	49.87	47.16	2.71	6.96	14.82
7	dstop1	90	48.41	46.00	2.42	6.33	4.02
8	dstop2	0	30.91	29.62	1.29	5.43	4.28
9	dstop2	90	29.24	27.00	2.24	4.51	5.11
10	flange	0	181.89	168.95	12.94	14.23	14.98
11	flange	90	180.62	172.14	8.48	15.81	9.83
12	hlatch	0	164.99	161.26	3.73	11.17	11.94
13	hlatch	90	167.32	158.19	9.13	8.87	14.90
14	ladder	0	25.25	22.50	2.75	15.23	12.33
15	ladder	90	23.98	20.90	3.08	5.42	1.88
16	nkhang	0	133.77	127.59	6.18	9.80	10.30
17	nkhang	90	148.39	137.64	10.75	20.98	14.90
18	runleg	0	187.23	177.04	10.19	28.22	7.18
19	runleg	90	201.71	162.07	39.64	23.92	14.96
20	tkwren	0	51.25	48.75	2.50	4.25	14.57
21	tkwren	90	58.36	54.33	4.03	9.37	6.94
22	unwren	0	41.35	36.38	4.97	11.35	4.55
23	unwren	90	34.80	29.18	5.62	5.57	14.74