



Conditions of Fukushima Dai-ichi Nuclear Power Stations **Unit 1**

(As of 14:00 March 18th, 2011)




Conditions of Fukushima Dai-ichi Nuclear Power Stations **Unit 2**

(As of 14:00 March 18th, 2011)




Conditions of Fukushima Dai-ichi Nuclear Power Stations **Unit 3**

(As of 14:00 March 18th, 2011)



Conditions of Fukushima Dai-ichi Nuclear Power Stations **Unit 4** (As of 14:00 March 18th, 2011)



Major events after the earthquake

In periodic inspection outage when the earthquake occurred.


14th 4:08 Water temperature in the Spent Fuel Pool, 84°C

15th 6:14 Damage of wall in the 4th floor confirmed

15th 9:38 Fire occurred in the 3rd floor (12:25 extinguished)

16th 5:45 Fire occurred. TEPCO couldn't confirm any fire on the ground. (7:26 extinguished)

Conditions of Fukushima Dai-ichi Nuclear Power Stations Unit 5/6 (As of 14:00 March 18th, 2011)



Current Conditions: Emergency Diesel Generator (1 unit) for Unit 6 is being operated (supplying electricity to Units 5 and 6)

Future Operation: Start operating for recovery of external power

※ As of 13:00 March 18th